

## FIRST RE-ESTABLISHMENT

GCDB 340400

Quarter corner common to Sections 16 and 21, Township 39 South, Range 3 East, W.M.

I located the point for this corner by reference to the BTs, using distance as control. Set 1" x 36" pipe to mark and perpetuate the corner.

From which:

- 16" Yellow Pine bears N37½°E, 19.8 feet (this is an original BT and is described as "20" Pine - N26°E 30 links).
- A 60" Yellow Pine bears S57°W, 19.14 feet (this is an original BT, now badly burned out at the butt described as "60" Pine bears S41°W, 29 links).
- Set 10" Red Fir scribed CS-BT, which bears S21°E, 19.3 feet.

July 28, 1938  
L. E. Smith,  
Deputy Surveyor

C. Bourne, Chainman

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

## SECOND RE-ESTABLISHMENT

GCDB 340400

Quarter corner common to Sections 16 and 21, Township 39 South, Range 3 East, W.M.

Found the 1" iron pipe disturbed by logging, reset in proper position from Yellow Pine stump, plainly scribed, which bears N38°E, 19.8 feet to upper blaze

- An 18" Fir with two blazes which bears S22°E, 19.0 feet to the face of the tree.
- The 60" Pine has fallen but stump hole is reasonable as reported in re-establishment records.

Scribed a 16" Fir CS-BT which bears N54½°E, 64.4 feet to the face of the lower blaze.

October 19, 1967  
Gary Kaiser

L. D. Pinkham,  
Deputy County Surveyor

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

### THIRD RE-ESTABLISHMENT

GCDB 340400

Quarter corner common to Sections 16 and 21, Township 39 South, Range 3 East, W.M.

Found flush with the ground, in large mound of stones, the 1 x 36-inch iron pipe set on First Re-establishment in 1938 and reset on Second Re-establishment in 1967.

In top of said pipe, projecting 6 inches, is a  $\frac{5}{8}$ -inch rebar (Survey No. 4191, dated 1970) with aluminum cap marked:

WEYERHAEUSER  
16  
 $\frac{1}{4}$ S —  
21  
1969  
ORLS 6 6

Replaced said monument (s) with and deposited alongside a 1 x 36-inch diameter galvanized iron pipe, set 32 inches in the ground, with a 2½-inch diameter brass cap marked:

T39S R3E  
16  
 $\frac{1}{4}$ S —  
21  
C.S.  
1986

Original bearing trees recorded by S. Truax, in 1859 and reported on subsequent re-establishments found:

- Forked Pine stump, about 36-inch diameter at base, containing scribed "s" in upper and "BT" in lower face, bears as noted in 1967; N38°E, 19.8 feet to scribed upper face. Re-measured, 20.10 feet to scribed lower face.
- Partial shell of a burned out pine stump, approximately 60-inch diameter, bears as recorded in 1938, S57°W 19.14 feet to estimated position of original face.
- **Note:** In 1938, a conflict with the original record was discovered and record distances were used "as control".

A bearing tree marked on First Re-establishment:

- A Douglas Fir, now 26-inch diameter with healed blazes, bears S22°E 19.88 feet to center of tree at lower blaze. Record S21°E, 19.3 feet.

A bearing tree marked on Second Re-establishment:

- A White Fir, now 23-inch diameter, with healed blazes, bears N54½°E 64.86 feet. Record 64.4 feet.

Corner lies on gentle (30%) Southwest slope, 8 feet South of foot trail and an estimated 250 feet S30°W of location marker on wood guardrail post near middle of switchback on Hyatt-Prairie Road.

August 6, 1986  
R. Frost  
T. Newcomb

Edward McGinty  
County Surveyor

V = 21 ¾°