

FIRST RE-ESTABLISHMENT

GCDB 340700

Quarter corner common to Sections 33, Township 38 South, Range 3 East, and Section 4, Township 39 South, Range 3 East, W.M. $V = 20^\circ$

From the following evidence, at the location described below, I set a 1 x 36-inch G.I. pipe, 28 inches in the ground with a 2½-inch bronze disc marked:

Jackson County 1976
T38S R3E
33
¼S —
4
T39S

Original BTs recorded by S. Truax in 1859, found as follows:

- A rotted Fir stob, 24-inch diameter, scribed "¼S" in opened upper face, bears $S39^\circ W$, 40.92 feet to scribed face. Record: $S49^\circ W$, 40.92 feet.
- Fir snag, 22-inch diameter, scribed "¼" in partially exposed face, bears Record: $N50^\circ W$, 11.88 feet to scribed face.

I mounded stones around corner, marked new trees CS BT and took measurements to center of trees at lower blaze:

- White Fir, 22-inch diameter, bears $S20^\circ E$, 17.35 feet.
- White Fir, 15-inch diameter, bears $N39\frac{1}{4}^\circ W$, 44.68 feet.

Corner lies 50 feet West of road C. N-S.

June 21, 1976
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor