

FIRST RE-ESTABLISHMENT

GCDB 400300

Section corner common to Sections 21, 22, 27, 28 and Township 39 South, Range 3 East, W.M.
 $V = 18\frac{1}{2}^\circ$

Found 2-inch diameter pipe (leaning South, 12°) projecting 24 inches from a mound of stone with GLO brass cap marked as described by F. W. Rodolf on First Re-establishment in 1917:

| | |
|------|-----|
| T39S | R3E |
| S21 | S22 |
| S28 | S27 |

Original BTs recorded by S. Truax in 1859:

- A rotted Fir stump, approximately 30-inch diameter, containing chain notch and scribed "BT", bears Record: $S63^\circ E$, 18.48 feet to center.
- A rotted Fir stump shell, approximately 36-inch diameter, containing reverse impression of scribed "BT", bears $N56\frac{1}{2}^\circ E$, 17.16 feet to center. Record: $N62^\circ E$, 17.16 feet.

BT marked by Rodolf in 1917 found as follows:

- A sawed Fir stump, 66-inch diameter, with healed lower blaze and section alongside containing reverse impression of scribed "R3E", bears record, $S25^\circ W$, 93.72 feet to center.
- NW BT has been destroyed by tractor.

I marked new trees CS BT and took measurements to center of tree at lower blaze:

- A Douglas Fir, 17-inch diameter, bears $N68\frac{1}{2}^\circ E$, 33.9 feet.
- A White Fir, 12-inch diameter, bears $S18\frac{1}{2}^\circ E$, 53.6 feet.
- A White Fir, 14-inch diameter, bears $S35^\circ W$, 15.5 feet.
- A White Fir, 13-inch diameter, bears $N15^\circ W$, 25.8 feet.

Corner lies about 165 feet East of location marker on 7-inch diameter White Fir, alongside road.

July 23, 1974
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 400300

Section corner common to Sections 21, 22, 27 and 28 Township 39 South, Range 3 East, W.M.

Found at the corner position, exposed 17 inches and in a mound of stones, the 2-inch diameter galvanized iron pipe with 2½-inch diameter brass cap recorded by F. W. Rodolf of the GLO in 1917, marked:

| | |
|-------|-----|
| T39S | R3E |
| S21 | S22 |
| <hr/> | |
| S28 | S27 |

Said pipe leaning south 12° per First Re-establishment.

Bearing trees recorded on First Re-establishment in 1974 found and measured to center of trees at lower blaze:

- Douglas Fir, now 28-inch diameter with double healed blazes bears Record: N68½°E, 33.9 feet.
- Down, rotted fir bears S18½°E, 53.4 feet to center of stump hole. Record: 53.6 feet.
- White Fir, now 20-inch diameter with double healed blazes bears S35½°W, 15.4 feet. Record: S35°W, 15.5 feet.
- Down, rotted fir bears Record: N15°W, 25.8 feet to center of stump hole.

Marked new bearing trees "CS" "BT" and took measurements to center of trees at lower blaze:

- White Fir 6-inch diameter bears S66½°E, 11.7 feet.
- White Fir 15-inch diameter bears N47°W, 79.0 feet.

Corner lies approximately 165 feet east of location marker on 14-inch diameter White Fir alongside paved road.

May 16, 2005
H. Durkee

Roger R. Roberts
Jackson County Surveyor

P. - 54
V. - 15°05'