

FIRST RE-ESTABLISHMENT

GCDB 400540

Quarter corner common to Sections 9 and 10, Township 39 South, Range 3 East, W.M.

Found a $\frac{3}{4}$ " iron pin for corner, set on Recorded Survey No. 3544.

Set a 1" x 36" galvanized iron pipe, directly over the pin, driven 32" in the ground with a 2½" bronze cap stamped:

T39S, R3E
¼ 9 | 10 Cor.
C.S.
1967

From which:

- A 30" Fir stump with BT scribe bears N59°W, 4.0 feet to the scribed face.
- A 24" Fir snag, plainly scribed in both blazes, bears S41°E, 4.6 feet to the face of the lower blaze.

Marked the following new trees:

- An 8" Fir scribed CS-BT bears N8°W, 30.8 feet to the face of the upper blaze.
- A 16" Fir scribed CS-BT bears N87°E, 38.4 feet to the face of the lower blaze.

November 6, 1967
Gary Kaiser

L. D. Pinkham,
Deputy County Surveyor

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 400540

Quarter corner common to Sections 9 and 10 of Township 39 South, Range 3 East, W.M.

Found at corner position exposed 3 inches the 1-inch diameter galvanized iron pipe with a 2½-inch diameter brass cap set on First Re-establishment in 1967 and marked:

T39S R3E
¼ 9 | 10 Cor.
C.S.
1967

Tri-pod steel fence posts 1 foot southerly.

Bearing trees recorded on said First Re-establishment found and measured to center at lower blaze:

- White Fir now 26-inch diameter with healed double blazes bears Record: N 8° W, 30.8 feet.
- White Fir now a burned stump bears Record: N 87° E, 38.4 feet.

Marked new bearing trees "CS" "BT" and measured to center at lower blaze:

- White Fir 9-inch diameter bears N 66° E, 10.1 feet.
- White Fir 12-inch diameter bears N 61° W, 25.7 feet.
- White Fir 8-inch diameter bears S 50° W, 40.9 feet.
- Large trees found in southeast quadrant are on private property, none marked.

Corner lies approximately 200 feet northwesterly from the "Pierce" residence.

October 10, 2007

B. Beeman
H. Durkee

Roger R. Roberts
Jackson County Surveyor

P. - 230
V. - N/A

Hand compass used
due to magnetic
disturbance.