

FIRST RE-ESTABLISHMENT

GCDB 400700

Corner common to Sections 33 and 34, Township 38 South Range 3 East and Sections 3 and 4, Township 39 South Range 3 East.

Found a $\frac{3}{4}$ " x 29" iron pipe set for corner.

I replaced said pipe with a 1"x36" iron pipe, set 32" in the ground with brass cap stamped:

T38 & 39 SR3E	
33	34

4	3
Sec.	Cor.
C.S. 1961	

For corner, from which:

- The original witness tree (now a 16" fir snag plainly scribed "S4" bears South 36° West, 20.6 feet.
- The original witness tree (now a 24" White Fir plainly scribed "T39S3" bears South 55° East, 8.0 feet.
- Also found the stumps of the Northwest and Northeast witness trees in proper relation, finding the "BT" scribe in the North-west stump.

I marked new trees as follows:

- An 8" White Fir, scribed "CS-BT" bears North 73° East, 22.0 feet to the face of the lower blaze;
- A 10" White Fir, scribed "CS-BT" bears North 55½° West, 9.2 feet to the face of the lower blaze;
- A 14" White Fir, scribed "CS-BT" bears South 17½° West, 29.4 feet to the face of the lower blaze;
- An 8" White Fir, scribed "CS-BT" bears South 23° East, 7.2 feet to the face of the upper blaze.

Var. used: 21° East
June 21, 1961
M. E. Boyden,

County Surveyor
N. A. Newton