


FIRST RE-ESTABLISHMENT

GCDB 500100

Section corner common to Sections 34 and 35, Township 39 South, Range 3 East, and Section 2 and 3, Township 40 South, Range 3 East, W.M. $V = 20^\circ$

Found apportioned corner, an iron pipe 2-inch diameter, projecting 16 inches with attached GLO brass cap marked:



Set by F. W. Rodolf in 1917.

Trees recorded by Rodolf found as follows:

- A sawed Fir stump, 60-inch diameter, marked "9SR3E S35" (apparently knife carved) bears Record: $N21^\circ E$, 33.0 feet.
- A sawed Fir stump, 44-inch diameter, bears record, $S43^\circ E$, 85.8 feet.
- A rotted Cedar stump bears record, $S45^\circ W$, 66.0 feet.
- A Fir, 30-inch diameter, marked "S3" (knife carved) in opened upper face, bears record, $N14^\circ W$, 26.4 feet.

I marked the following trees CS BT and took measurements to center of trees at lower blaze:

- A White Fir, 14-inch diameter, bears $N32^\circ E$, 30.9 feet.
- A White Fir, 12-inch diameter, bears $S67^\circ E$, 23.1 feet.
- A White Fir, 14-inch diameter, bears $S22^\circ W$, 44.1 feet.
- A Douglas Fir, 10-inch diameter, bears $N33\frac{1}{2}^\circ W$, 26.6 feet.

Corner lies 55 feet East of location marker on 6-inch diameter Cedar alongside skid road.

October 16, 1973
B. Malotte
E. Graham
R. Frost

Approved by: Edward McGinty
County Surveyor