

FIRST RE-ESTABLISHMENT

GCDB 500640

Quarter corner common to Sections 2 and 3, Township 39 South, Range 3 East, W.M.

Set a 1" x 36" galvanized iron pipe, with 2½" bronze cap, driven 24" in the ground and raised a mound of stone - said cap stamped:

T39S R3E
¼ 3 | 2 Cor.
C.S.
1967

From which:

- The center of a stump hole of a down Fir snag, with BT scribe on a pitched slab, bears S89°E, 31.3 feet.
- A 36" Fir with blazes intact bears S65°W, 31.1 feet to the face of the tree.
- Scribed a 26" Fir CS-BT which bears N56½°E, 10.6 feet to the face of the lower blaze.

November 6, 1967
Gary Kaiser

L. D. Pinkham,
Deputy County Surveyor

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 500640

Quarter corner common to Sections 2 and 3, Township 39 South, Range 3 East, W.M.

Found projecting 6 inches, the 1-inch diameter iron pipe with 2½-inch diameter brass cap marked:

T39S R3E
¼ 3 | 2 cor.
C.S.
1967

Reported set on First Re-establishment, page 7, in 1967.

Original bearing tree marked by Sewell Truax in 1859 found:

- Fir snag, now 36-inch diameter with healed blazes, bears Record: S65°W, 31.68 feet to estimated lower face. Measured 31.1 feet to face of tree.

Bearing tree marked on First Re-establishment found:

- Douglas Fir, now 26-inch diameter with double healed blazes, bears Record: N56½°E, 10.6 feet to estimated lower face. Re-measured 11.55 feet to center of tree at lower blaze.

Marked a new tree "CS" "BT":

- White Fir, 20-inch diameter, bears N74½°W, 39.10 feet to center of tree at lower blaze.

Corner lies on gentle northeast slope, an estimated 1500 feet North of the intersection of roads at the north end of Hyatt Reservoir.

December 2, 1986
D. Edwards
R. Romio

Edward McGinty
County Surveyor

V = 18½°
P.-341