

FIRST RE-ESTABLISHMENT

GCDB 540100

Quarter corner common to Section 35, Township 39 South, Range 3 East, and Section 2, Township 40 South, Range 3 East, W.M. $V = 20\frac{1}{4}^\circ$

Found iron pipe (1 x 36ins.) with attached GLO brass cap marked:

S35
¼S —
S 2
1917

This monument recorded by F. W. Rodolf as marking the apportioned location of ¼ cor. As determined in 1917 resurvey, was found as follows:

- That portion of the pipe projecting (22ins.) from the ground was bent in an "S" shape, the attached cap turned approximately 45 degrees.
- The original splayed lower end of the pipe had been reclosed.
- There have been a number of logging operations (6) in the general area recorded by the State Forestry Dept.
- A corner report on file at Medford BLM office dated 5-28-64 states "Brass cap is torn out of ground laying on ground".
- As the 1917 BTs noted below do not agree favorable with the found position and in consideration of the fore-going facts, I determine the monument location has been altered by an unknown person.

To perpetuate the recorded location, I removed, straighten, and reset the pipe with attached brass cap, 26 inches in the ground.

From which:

- An original (1917) BT, a Pine, now 38 ins. diam., with healed blaze, bears record, N10°E, 10.56 feet to estimated face.
- An original (1917) BT, now a Fir stob, with section of tree alongside, scribed as recorded "¼ S2 BT", bears record, S35°W, 43.56 feet to estimated face.
- The found location of subject monument bears S53°E, 2.48 feet.

I marked a new tree CS BT and took measurements to center of tree at lower blaze:

- A White Fir, 12ins. diam., bears S48½°W, 31.44 feet.

SEE Jackson County Corner Report, dated 11/21/78 on file. (R. Frost)

October 22, 1973
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor

SECOND RE-ESTABLISHMENT

GCDB 540100

Quarter corner common to Section 35, Township 39 South Range 3 East, and Section 2, Township 40 South Range 3 East, W.M.

Found the 1 ins. diam. galvanized iron pipe with a faded Jackson County yellow pastic cap inside, per the Corner Report dated 11/21/78 on file (R. Frost). Corner is flush in a 3 foot diam. by 6 ins. high mound of stones.

Found original (1917) Bearing Trees:

- A Pine, 43ins. diam., with healed blaze, bears Record N10°E, 10.56 feet to side center at lower blaze (not estimated face).
- A now well rotted Fir stob, with remains of face ("S2 BT" visible), bears Record S35°W, 43.56 feet to physical center (not estimated face).

Found Bearing Tree marked on First Re-Establishment in 1973:

- A White Fir, 18 ins. diam. (dead and down), bears S53°W, 32.10 feet to stump hole. Record S48½°W, 31.44 feet.

Marked new Bearing Trees "CS" in upper and "BT" in lower blaze and measure to center of tree at lower blaze:

- Cedar, 18 ins. diam., bears S40°E, 39.28 feet
- White Fir, 15 ins. diam., bears S44°W, 56.30 feet
- Ponderosa Pine, 11 ins. diam., bears N78°E, 48.18 feet

May 11, 2017
S. Fein
J. Hall

Scott Fein
Jackson County Surveyor

P. -
V = 15°