

SECOND RE-ESTABLISHMENT

GCDB 600200

Section corner common to Sections 25, 26, 35 and 36, Township 39 South, Range 3 East, W.M.
V = 13°

Found 2-inch diameter Galvanized iron pipe projecting 12 inches with GLO brass cap marked as recorded on 1917 re-establishment by F. W. Rodolf:

T39S	R3E
S26	S25
S35	S36
1917	

Original BTs marked by S. Truax in 1859 and noted by Rodolf in 1917 found as follows:

- A Sugar Pine, 37-inch diameter, with healed blazes, bears Record: N47°E, 37.62 feet to estimated face of blaze. Re-measured 38.8 feet to center.
- A double Sugar Pine, 50-inch diameter, with healed blazes, bears Record: N27°W, 24.42 feet to estimated face on East side of tree. (Center of tree bears N28°W, 24.4 feet.)
- The rotted stump remains of down Fir, 20-inch diameter, with healed blazes, bears S38°E, 27.3 feet. Record: S30°E, 25.74 feet.
- The rotted stump of a down White Fir, 24-inch diameter, bears S37°W, 31.68 feet on slope. Record: S47°W, 31.68 feet.

I marked new trees CS BT and took measurements to center of trees at lower blaze:

- A White Fir, 11-inch diameter, bears S65½°E, 15.0 feet.
- A Cedar, 8-inch diameter, bears S70¼°W, 18.35 feet.

Corner lies 800 feet West of location marker on 8-inch diameter White Fir, on N.E. side of road.

August 8, 1974
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor