

FIRST RE-ESTABLISHMENT

GCDB 600400

Section corner common to Sections 13, 14, 23 and 24 of Township 39 South, Range 3 East, W.M.

Found at the corner position, exposed 7 ins., in a mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1967 and marked:

T39SR3E
S14 | S13
—+—
S23 | S24
1967

Original bearing trees recorded by Sewall Truax of the GLO in 1859 found with healed blazes and measured to center at base;

- W. fir now 32 ins. diam. brs. record; S25°E, 37.0 ft.
- W. fir snag with opened upper blaze with scribe 'S23' brs. S3°W, 33.0 ft. record; S4°W.
- W. fir snag down and rotted brs. record; N78°W, 25.7 ft.

Bearing trees recorded by the BLM in 1967 found with healed single blazes and measured to center at base;

- D. fir now 29 ins. diam. brs. N40°E, 5.6 ft. record; N36°E.
- Cedar now 13 ins. diam. brs. record; N84°W, 60.1 ft.

Marked new bearing tree 'CS''BT' and measured to center at lower blaze;

- Cedar 10 ins. diam. brs. S56°W, 16.0 ft.

Corner lies approx. 600 ft. northerly along blocked road to gate, then approx 650 ft. north.

November 5, 2009

B. Beeman
H. Durkee

Kerry K. Bradshaw
Jackson County Surveyor

P. – 250
V. – 16°15'