

FIRST RE-ESTABLISHMENT

GCDB 640700

Quarter corner between Section 36, Township 38 South, Range 3 East and Section 1, Township 39 South, Range 3 East.

Located the corner by reference to BT to N.E. now dead. Found stump hole and BT scribe on floating stump, rotted out.

Set a 1"x36" gas pipe for corner from which:

- A 14" red fir scribed "C.S.-BT" bears N56°E 44.2 feet and a 12" red fir scribed "C.S.-BT" bears S72½°W, 42.0 feet.

July 16, 1938
L. E. Smith Deputy Surveyor

C. Bourne, Chainman
Walter Hartle, Chainman

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 640700

Quarter corner common to Section 36, Township 38 South, Range 3 East, and Section 1, Township 39 South, Range 3 East, W.M.

Found, 36 inches deep, the 1-inch diameter iron pipe, set by L. E. Smith on First Re-establishment in 1938.

Original BTs are now gone. BTs marked by Smith found as follows:

- Red Fir, 18-inch diameter, scribed "CS" "BT" in exposed faces, bears N56°E, 44.10 feet to scribed lower face. Record, N56°E, 44.2 feet.
- Douglas Fir, 17-inch diameter, with scribe marks visible in exposed upper face, bears S72½°W, 42.27 feet to center. Record: S72½°W, 42.0 feet.

I marked a new tree CS BT:

- White Fir, 8-inch diameter, bears N27°W, 51.44 feet to center of tree at lower blaze.

Corner lies on E-W fence line (3.5 feet West of most Westerly wood anchor post) and about 40 feet North of paved road.

June 22, 1976
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor

NOTE: 1 x 36" G.I. Pipe set at corner, projecting 6" with brass cap marked:

Jackson County 1976
T38S R3E
36
¼S —
1
T39S

RF: 2-5-81

THIRD RE-ESTABLISHMENT

GCDB 640700

Quarter corner between Section 36, Township 38 South, Range 3 East and Section 1, Township 39 South, Range 3 East

Found the 2½-inch brass cap in a small ring of stone, 5 inches above surface as reported on February 5, 1981. Marked:

T38S R3E
36
¼S —
1
T39S
1976

References found:

- 13-inch diameter White Fir. (Record 8-inch), with healed blazes, upper and lower. Bears: N27°W (Record: 51.39 feet) (Record: 51.44 feet.)
- 26-inch diameter Red Fir (Record 18-inch), high stump with healed blazes, upper and lower Bears: N54°40"E, 44.26 feet (Record: N56°E, 44.2 feet.)

New References:

- 14-inch diameter Douglas Fir, marked: Upper blaze "CS"; lower blaze "BT" Bears: N53°18'E, 47.14 feet.
- Forked Ponderosa Pine, 21-inch diameter N. fork, by 19-inch diameter S. fork. South fork with upper blaze "CS" lower blaze "BT" Bears: S 59°37'E, 34.99 feet.
- Mag nail with washer set on N. edge asphalt, Howard Dam Road, Bears: S3°10'59"W, 32.20 feet.
- 19-inch diameter White Fir, with upper blaze "CS", lower blaze "BT", Bears: S72°34'W, 24.57 feet.

Placed steel fence post with sign 1 foot N. of corner.

Corner lies in a partially down E-W fence, approximately 40 feet N. or Howard Dam Road, and ½ mile east of the intersection of Hyatt Prairie Road and Howard Dam Road.

July 1, 2008
S. Fein

Roger Roberts
County Surveyor

Book II Series I,
P-13