

FIRST RE-ESTABLISHMENT

GCDB 700700

Township corner to Township 38 South, Range 3 East and 4 East and Township 39 South, Range 3 and 4 East.

I found all the original bearing trees for this corner to be in excellent condition at the point determined.

From said bearing trees I set a 2"x36" pipe to mark and perpetuate the corner.

July 16, 1938
L. E. Smith,
Deputy Surveyor

C. Bourne, Chainman
Walter Hartle, Chainman

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 700700

Township corner common to Section 31, Township 38 South, Range 4 East, Section 36, Township 38 South, Range 3 East, Section 1, Township 39 South, Range 3 East, and Section 6, Township 39 South, Range 4 East.

At the corner, found projecting 6 inches in mound of stone, a 2-inch diameter iron pipe with standard 2½-inch diameter BLM brass cap marked:

T38S	
R3E R4E	
S36	S31

S1	S6
T39S	
1957	

Original bearing trees recorded by S. Truax in 1859 found:

- The center of stump remains of a down Pine, 36-inch diameter, scribed "8SR4E31" and "B" in partly exposed faces, bears N41°40'E, 50.01 feet. Record: N41°E, 48.84 feet.
- Rotted Pine stump, 26-inch diameter, scribed "BT" in exposed face, bears S49°35'E, 36.50 feet to scribed face. Record: S50°E, 37.62 feet.
- Sawed Fir stump, 36-inch diameter containing scribe marks in partially exposed face, bears S65°W, 22.37 feet to scribed face. Record: 21.78 feet.

Bearing trees marked by BLM in 1957 found and measurements taken to center of trees at healed single blaze:

- White Fir, 20-inch diameter, bears N72°E, 43.78 feet. Record: 44.88 feet.
- White Fir, 16-inch diameter, bears S45°30'E, 31.70 feet. Record: 33.00 feet.
- White Fir, 12-inch diameter, bears N74°15'W, 20.00 feet. Record: N74½°W, 19.80 feet.

Marked a new tree "CS" "BT":

- White Fir, 8-inch diameter, bears S60°40'W, 5.70 feet to center of tree at lower blaze.

Pipe set on First Re-establishment, page 1, (T38SR3E), in 1938, is not found.

Corner lies 1 foot West of the Wood post corner of South and East bearing fence lines.

May 26, 1981
R. Frost

Edward McGinty
County Surveyor

V = 21°
P. -86

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

**THIRD RE-ESTABLISHMENT
GCDB 700700**

Township corner common to Section 31, Township 38 South, Range 4 East, Section 36, Township 38 South, Range 3 East, Section 1, Township 39 South, Range 3 East, and Section 6, Township 39 South, Range 4 East. V = 19½°

At the corner, fd. projecting 6 ins. and leaning easterly in small mound of stone, a 2 ins. diam. iron pipe with 2 ins. diam. G.L.O. brass cap (set by and noted as a Bureau of Land Management cap on the Second Re-establishment dated 1981) mkd:

T38S
R3E R4E
S36 S31

S1 S6
T39S
1957

Original bearing tree marked by S. Truax in 1859 found;

- Fir Stump 36 ins. diam. with scribe marks visible on exposed face brs. Second Re-establishment record S65°W, 22.37 ft. to exposed face

Bearing trees marked by the Bureau of land management in 1957 found and measured to the center of tree at single blaze;

- White fir snag 21 ins. diam. 10 ft. high with healed blaze brs. N72°E, 43.60 ft. Second Re-establishment record 43.78 ft.
- White fir snag 19 ins. diam. with healed blaze brs. S45½°E, 31.80 ft. Second Re-establishment record 31.70 ft.
- White fir snag 15 ins. diam. with healed blaze brs. N74°W, 20.20 ft. Second Re-establishment record N74°15'W, 20.00 ft.

Second re-establishment bearing tree found;

- White fir 13 ins. diam. with healed double blaze brs. S61°W, 5.88 ft. to center of tree at lower blaze. Record S60°40'W, 5.70 ft.

Mark new trees 'CS BT' and measure to center of tree at lower blaze;

- Douglas Fir 14 ins. diam. brs. N89¾°E, 34.50 ft.
- Ponderosa Pine 7 ins. diam. marked 'X BT' brs. S10°E, 74.60 ft.
- Ponderosa Pine 12 ins. diam. brs. N67°W, 29.45 ft., lower blaze off center.

Note: Fir tree 1.50 ft. to northwest of monument may be pushing monument.

March 18, 2010
S. Beecher
S. Fein

Kerry K. Bradshaw
County Surveyor

P.-32
Series II Book I