

**FIRST RE-ESTABLISHMENT
CORNER COMMON TO SECTIONS 31 AND 32 ONLY
GCDB 200100**

Standard corner common to Sections 31 and 32, Township 39 South, Range 4 East, W.M. $V = 17^\circ$

Found in a ring of stone, a 3/4 x 22-inch iron pipe, projecting 6 inches. Reference: R.S. No. 2801, dated 1964.

I replaced said pipe with a 1 x 36-inch Galvanized iron pipe set 28 inches in the ground with a 2½-inch bronze disc marked:

Jackson County 1974
T39S R4E
S31 | S32

S.C.
T40S

Original BTs marked by E.T.T. Fisher in 1858 found as follows:

- A Pine stump core, 18-inch diameter, with burned axe face bears Record: $N37^\circ E$, 88.44 feet to burned face.
- The base of a down and rotted Fir, about 30-inch diameter scribed "R4" in exposed upper face bears Record: $S60^\circ W$, 21.12 feet.

I mounded stones around corner, deposited found pipe alongside, marked the following trees CS BT, and took measurements to center of tree at lower blaze:

- A Ponderosa Pine, 13-inch diameter bears $N50\frac{1}{2}^\circ E$, 27.33 feet.
- A Douglas Fir, 9-inch diameter bears $S84^\circ E$, 33.87 feet.
- A Ponderosa Pine, 10-inch diameter bears $S31^\circ W$, 19.65 feet.
- A Douglas Fir, 11-inch diameter bears $N73\frac{1}{2}^\circ W$, 28.44 feet.

Corner lies $S73^\circ W$, 12.0 feet from the corner of North, West and Southeast bearing fence lines.

December 18, 1974
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor