

FIRST RE-ESTABLISHMENT

GCDB 200200

Section corner common to Section 29, 30, 31 and 32, Township 39 South, Range 4 East, W.M.
V = 18°

Found, ¾ x 30-inch iron pipe, projecting 6 inches in a mound of stone.

Reference: Survey No. 2801, dated 1964.

I replaced said pipe with a 1 x 36-inch Galvanized iron pipe set 28 inches in the ground with a 2½-inch bronze disc marked:

Jackson County 1975	
T39S	R4E
30	29
31	32

And deposited found pipe alongside.

Original BTs marked by S. Truax in 1859, found as follows:

- A down and rotted Fir, found at record location of NE BT.
- Pine snag, 40-inch diameter, scribed "S32" and "BT" in exposed faces bears Record: S7°E, 48.18 feet to scribed lower face.
- Ponderosa Pine, 15-inch diameter, (the corner of South and East bearing fence lines) scribed "9S 31" in exposed upper face bears S65°W, 1.98 feet to scribed face. Record S45°W, 1.98 feet.
- The base of a down and rotted Pine, about 8-inch diameter, scribed "4E S30 in exposed face, bears Record: N60°W, 6.60 feet.
- **Note:** Original SE and SW BTs have "W" nail in base.

I marked new trees CS BT and took measurements to center of trees at lower blaze:

- Douglas Fir, 8-inch diameter bears N35½°E, 25.69 feet.
- Douglas Fir, 15-inch diameter, with "W" nail in base bears S33½°E, 45.00 feet.
- Douglas Fir, 11-inch diameter bears N52°W, 31.57 feet.

Corner lies about 650 feet West of location marker on 8-inch diameter Juniper, alongside road at fence crossing.

August 6, 1975
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor