

## FIRST RE-ESTABLISHMENT

GCDB 200600

Section corner common to Sections 5, 6, 7 and 8 of Township 39 South, Range 4 East, W.M.

Found at corner position exposed 8 inches, with original stone alongside, the 2-inch diameter galvanized iron pipe with the 2½-inch diameter brass cap set by the BLM in 1957, marked:

T39S	R4E
S6	S5
<hr/>	
S7	S8
1957	

Original bearing trees recorded by Sewall Truax of the GLO in 1859 found with healed double blazes and measured to center at base:

- Pine, now 33-inch diameter bears N 55° E, 62.0 feet. Record: 61.4 feet to face.
- Pine sawed stump bears S 22° E, 17.4 feet. Record: 17.2 feet to face.
- Pine, now 35-inch diameter bears S 61½° W, 18.0 feet. Record: S 60° W, 17.2 feet to face

Bearing tree recorded by the BLM in 1957 with healed single blaze, dead and down, found and measured to center of stump hole:

- Douglas Fir bears Record: N 26° W, 40.9 feet.

Marked new bearing trees with "CS" and "BT" and measured to center at lower blaze:

- Douglas Fir 15-inch diameter bears N 18¼° W, 50.5 feet.
- Douglas Fir 10-inch diameter bears S 80¾° E, 24.9 feet.

Corner lies approximately 70 feet south of Pacific Crest Trail and approximately 200 feet southwesterly of intersection of Howard Prairie Dam Road and gravel road to Johnson Prairie.

September 26, 2006

B. Beeman

H. Durkee

Roger R. Roberts

Jackson County Surveyor

P - 163

V - 16°