

FIRST RE-ESTABLISHMENT

GCDB 200700

Section corner common to Sections 31 and 32, Township 38 South, Range 4 East and Sections 5 and 6, Township 39 South, Range 4 East, W.M.

Found projecting 14 inches, the 2-inch diameter iron pipe with the standard GLO 2½-inch diameter brass cap marked:

T38S	R4E
S31	S32
S6	S5
T39S	
1957	

Bearing trees marked in 1957 found with single healed blazes and measured to the center of tree at base:

- Ponderosa Pine 21-inch diameter bears S68°W, 56.60 feet.
- Ponderosa Pine 16-inch diameter and broken off 2 feet high bears S55½°E, 44.70 feet.
- Other 2 bearing trees down and rotten, and could not determine their true location.

Marked new trees "CS" "BT" and took measurements to the center of tree at lower blaze:

- Ponderosa Pine, 5-inch diameter bears N7½°E, 28.00 feet.
- Ponderosa Pine, 7-inch diameter bears S86½°E, 36.51 feet.
- Ponderosa Pine, 7-inch diameter bears S22°E, 43.34 feet.

Corner lies about 50 feet South of old high water mark.

June 26, 1992
T. Newcomb, Tech.
H. Durkee, Tech.

Verlyn Thomas
County Surveyor

V = 18°

P. -52