

FIRST RE-ESTABLISHMENT

GCDB 300400

Section corner common to Section 16, 17, 20 and 21, Township 39 South, Range 4 East, W.M.
 $V = 23\frac{3}{4}^\circ$

Found, $\frac{5}{8}$ -inch diameter re-steel rod, projecting 10 inches in a mound of stone with aluminum cap marked as noted on Survey No. 5552, file date 1974, with notched original stone alongside.

Over said rod, I drove a 1 x 36-inch Galvanized iron pipe 18 inches in the ground, with a 2½-inch bronze disc marked:

Jackson County 1975	
T39S	R4E
17	16
20	21

And deposited found aluminum cap and original stone alongside.

Original BTs recorded by P. Applegate in 1893, found as follows:

- White Fir, 50-inch diameter, with healed blazes bears N18°E, 65.27 feet to center of tree.
Record: N18°E, 64.68 feet.
- Red Fir, 54-inch diameter, with healed blazes bears Record: S28°E, 38.94 feet to center of tree.
- White Fir stump shell, scribed "BT" bears Record: S21½°W, 54.78 feet.
- The stump hole of a down and rotted White Fir, about 22-inch diameter bears Record: N49°W, 15.18 feet.

I marked new trees CS BT and took measurements to center of trees at lower blaze:

- White Fir, 11-inch diameter bears S10°E, 8.98 feet.
- White Fir, 14-inch diameter bears S20°W, 31.65 feet.
- White Fir, 9-inch diameter bears N26½°W, 26.09 feet.

Corner lies about 250 feet West of location marker on 8-inch diameter Fir alongside road.

September 9, 1975
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor