

FIRST RE-ESTABLISHMENT

GCDB 300600

Section corner common to Sections 4, 5, 8, and 9 of Township 39 South, Range 4 East, W.M.

Found at the corner position, exposed 7 ins., with the original stone alongside, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1966 and marked:

T39SR4E
S5 | S4
—+—
S8 | S9
1966

Original bearing trees recorded by Peter Applegate of the GLO in 1893 found with healed blazes and measured to center at base;

- Cedar now 29 ins. diam. brs. S7°E, 39.6 ft. record; 40.3 ft.
- Cedar now 30 ins. diam. brs. S72°W, 31.4 ft. record; S69°W, 31.0 ft.
- Cedar now 28 ins. diam. brs. N23°W, 18.0 ft. record; 18.5 ft.

Bearing tree recorded by the BLM in 1966 found and measured to center of root hole;

- W. fir dead and down with a partially healed single blaze brs. record ; N50°E, 65.3 ft.

Marked a new bearing tree 'CS''BT' and measured to center at lower blaze;

- P. pine 7 ins. diam. brs. N58°E, 35.4 ft.

Corner lies approx. 70 ft. west of old dirt road.

May 19, 2010

B. Beeman

H. Durkee

Kerry K. Bradshaw

Jackson County Surveyor

P. -119

V. - 14°20'