

FIRST RE-ESTABLISHMENT

GCDB 300640

Quarter corner common to Sections 4 and 5, Township 39 South, Range 4 East, W.M.

Found at the corner position, protruding 6 inches and in a mound of stones, the 2½-inch diameter galvanized iron pipe with 3½-inch diameter brass cap set by the BLM in 1966, marked:

T39S R4E
¼
S5 | S4
1966

- Single remaining original bearing tree recorded by Peter Applegate in 1893, a cedar now 37-inch diameter with healed blazes bears S 58° W, 42.0 feet to center at lower blaze
Record: 41.58 feet to face of lower blaze.
- Single remaining bearing tree recorded by the BLM in 1966, a fir down and rotted bears
Record: S 86° W, 4.95 feet to center of stump hole.

Marked new trees "CS" "BT" and took measurements to center of tree at lower blaze:

- Sugar Pine, 10-inch diameter bears N 46¼° E, 24.4 feet.
- White Fir 10-inch diameter bears S 7° W, 29.7 feet.

Corner lies approximately 100 feet east of graveled road.

September 1, 2004

H. Durkee

Roger R. Roberts
Jackson County Surveyor

P. - 75

V. - 15°30'

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 300640

Quarter corner common to sections 4 and 5, Township 39 South, Range 4 East, W.M.

Found the Bureau of Land Management brass cap as noted on the first re-establishment in 2004, exposed 6 ins. in a mound of stone with a 2 ½ ins. diam. GIP and 3 ½ ins. diam. brass cap MKD;

USDI BLM
T39S R4E
¼
S5 S4
1966
CADASTRAL SURVEY

Bearing trees found per the first reestablishment:

- Cedar 40 ins. diam. with double healed blazes (Original Bearing Tree) Brs. S58°W, 41.10 ft. Record: S 58° W, 42.0 ft.
- S. Pine 12 ins. diam. snag with upper and lower partially healed blazes with "CS, BT" visible brs. N46 ¼°E, 24.40 ft. Record: N 46 1/4° E, 24.4 ft.

Mark new bearing trees with upper blaze "CS" and lower blaze "BT"

- Cedar 6 ins. diam. brs. N76 ½°E, 31.70 ft.
- S. Pine 17 ins. diam. brs. N55°W, 23.30 ft.

December 9, 2011

S. Fein

Kerry K. Bradshaw
County Surveyor

Series II, Book I
P. -45