

**FIRST RE-ESTABLISHMENT  
CORNER COMMON TO SECTIONS 4 AND 5 ONLY  
GCDB 300700**

Closing corner common to Sections 4 and 5, Township 39 South, Range 4 East, W.M.  $V = 19\frac{1}{4}^\circ$

Found, in mound of stone, the 16 x 8 x 6-inch stone (Record: 12x8x8-inch) marked with 4 grooves on the East and 2 on the West face. The stone had apparently been disturbed in the past and reset, as the lower (buried) half was found painted blue.

I replaced said stone with a 2 x 36-inch Galvanized iron pipe, set 24 inches in the ground with a 2½-inch bronze disc marked:

Jackson County 1975  
T39S R4E  
33  
—  
5 | 4  
CC

Original BTs found as follows:

- White Fir snag, 25-inch diameter, scribed "T39S R4E" and "BT" in exposed faces bears Record: S14°E, 10.56 feet to center of tree.
- The stump hole of a down Fir, 24-inch diameter bears Record: S31½°W, 76.56 feet.
- White Fir, 18-inch diameter, with healed blazes bears Record: N14°W, 15.84 feet to center of tree.
- White Fir snag, 25-inch diameter, scribed "T39S R4E" and "BT" in exposed face bears Record: S14°E, 10.56 feet to center of tree.
- The corner (BLM brass cap) of Sections 32 and 33 bears West 42.99 feet original record, 42.24 feet.

I deposited original stone alongside corner, marked new trees CS BT and took measurements to center of trees at lower blaze:

- White Fir, 9-inch diameter bears S10°E, 29.73 feet.
- White Fir, 7-inch diameter bears S21°W, 67.62 feet.

September 22, 1975  
B. Malotte  
R. Frost

Approved by: Edward McGinty  
County Surveyor

**SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT**

**SECOND RE-ESTABLISHMENT  
CORNER COMMON TO SECTIONS 4 AND 5 ONLY  
GCDB 300700**

Closing corner common to Sections 4 and 5, Township 39 South, Range 4 East, W.M.  $V = 16^\circ$

Found the 2 ins. diam. galvanized iron pipe with 2½ ins. diam. brass cap mkd.;

Jackson County 1975  
T39S R4E  
33  
—  
5 | 4  
CC

Protruding 7 ins. above ground set on the First Re-establishment in 1975.

A 2 ins. diam. aluminum cap mkd.;

T39S R4E  
CC S33  
—  
S5 | S4  
1978  
ORLS 1139

On ⅝ in. diam. rebar exposed 2 ins. set on Filed Survey No. 7636 brs. South, 0.92 ft.

Original bearing trees found;

- White Fir, 20 ins. diam. with healed blazes, brs. 1975 record  $N14^\circ W$ , 15.84 ft. to center of tree at base.

Bearing tree marked on Filed Survey No. 7636 found:

- White Fir, 16 ins. diam. with healed single blaze, brs.  $S10^\circ W$ , 29.30 ft. to center of tree at base.

Bearing tree marked in 1975 found;

- Fir stump, 21 ins. diam. with healed blaze, brs.  $S19^\circ E$ , 29.73 ft. to center of stump. Record brg.  $S10^\circ E$ .

Mark a new tree 'CS BT' and measure to center of tree at base;

- Ponderosa Pine, 8 ins. diam., brs.  $S75^\circ E$ , 48.20 ft.

The Bureau of Land Management brass cap for T38S R4E Sections 32 and 33 brs.  $N89^\circ W$ , 48.07 ft. 1975 record West, 42.99 ft.

Corner is located 200 ft. north of logging road.

November 15, 2011  
S. Beecher  
S. Fein

Kerry K. Bradshaw  
County Surveyor

P.-19  
Series II Book I