

FIRST RE-ESTABLISHMENT

GCDB 340200

Quarter corner common to Sections 28 and 33, Township 39 South, Range 4 East, W.M. $V = 19^\circ$

Found, in mound of stone, a $\frac{5}{8}$ -inch re-steel rod, with marked aluminum cap, set inside $\frac{3}{4}$ -inch iron pipe as reported on Survey No. 5552, file date 1974.

I drove, over said rod and pipe, a 1 x 36-inch Galvanized iron pipe 24 inches in the ground with a $2\frac{1}{2}$ -inch bronze disc marked:

Jackson County 1975
T39S R4E
 $\frac{1}{4}$ S 28
—
33

Original BTs recorded by S. Truax in 1859, found as follows:

- The stump hole of a down and decayed Pine, about 20-inch diameter, scribed " $\frac{1}{4}$ " and "BT" in opened face bears Record: $N12^\circ E$, 15.18 feet.
- Rotted Pine stump, 20-inch diameter, 8 feet high, scribed " $\frac{1}{4}S$ " and "BT" in exposed faces bears $S53^\circ E$, 42.90 feet, on slope, to scribed lower face. Record, $S63^\circ E$, 42.90 feet.

I deposited found aluminum cap alongside corner, marked new trees CS BT and took measurements to center of trees at lower blaze:

- Cedar, 17-inch diameter bears $N31^\circ E$, 40.3 feet.
- Douglas Fir, 9-inch diameter bears $S38\frac{1}{2}^\circ E$, 17.00 feet.

August 14, 1975
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor