

**FIRST RE-ESTABLISHMENT
CORNER COMMON TO SECTIONS 33 AND 34 ONLY
GCDB 400100**

Standard corner common to Sections 33 and 34, Township 39 South, Range 4 East, W.M. $V = 18^\circ$

Found in a mound of stone, projecting 12 inches, a 5/8-inch diameter re-steel rod with aluminum cap marked:

W.C.C.
T39S R4E
S33 S34

1974

I replaced the above with a 1 x 36-inch Galvanized iron pipe set 26 inches in the ground with a 2½-inch bronze disc marked:

Jackson County 1974
T39S R4E
S33 S34

S.C.
T40S

Original BTs marked by E.T.T. Fisher in 1858, found as follows:

- A Pine, 16-inch diameter bears record, $N40^\circ E$, 9.24 feet to estimated face of blaze.
- At record location of SE BT, a section of Pine, containing scribe marks, including "BT" was found.
- A Douglas Fir, 24-inch diameter, with healed blazes bears Record: $S5^\circ W$, 11.88 feet to estimated face of blaze.
- A Douglas Fir, 24-inch diameter, with healed blazes bears Record: $N20^\circ W$, 27.06 feet to estimated face of blaze.

I deposited found re-steel rod alongside corner and marked a new tree CS BT:

- A Douglas Fir, 13-inch diameter bears $S51^\circ E$, 46.20 feet.

Corner lies on West edge of ridge.

December 3, 1974
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor