

FIRST RE-ESTABLISHMENT

GCDB 400440

Quarter corner common to Sections 15 and 16 of Township 39 South, Range 4 East, W.M.

Found at corner position , exposed 6 ins., in a mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1966 and marked:

T39SR4E
¼
S16 | S15
1966

Single remaining original bearing tree recorded by Peter Applegate of the GLO in 1893 found with a partially healed blaze with illegible scribe and measured to center at base;

- P. pine now 57 ins. diam. brs. S57°E, 55.5 ft. record; 52.8 ft. to face.

Bearing trees recorded by the BLM in 1966 found with healed single blazes and measures to center at base;

- W. fir now 14 ins. diam. brs. S65°E, 18.5 ft. record ; S64°E
- W. fir dead and down brs. record N32°W, 16.8 ft. to center of root hole.

Marked new bearing trees "CS" "BT" and measured to center at lower blaze:

- W. fir 10 ins. diam. brs. N56°E, 47.7 ft.
- D. fir 10 ins. diam. brs. N58¾°W, 25.1 ft.
- D. fir 12 ins. diam. brs. S64°W, 8.0 ft.

Corner lies approx. 200 ft. east of spur road.

May 20, 2010

B. Beeman

H. Durkee

Kerry K. Bradshaw

Jackson County Surveyor

P. – 121

V. – 14°30'