

FIRST RE-ESTABLISHMENT

GCDB 400500

Section corner common to Sections 9, 10, 15 and 16, Township 39 South, Range 4 East, W.M.

Found at the corner position, the 2½-inch diameter galvanized iron pipe with a 3½-inch diameter brass cap set by the BLM in 1966, exposed 10 inches and marked:

T39S	R4E
S9	S10
S16	S15
1966	

Bearing trees recorded by the BLM in 1966, found and measured to center of trees at base:

- Fir snag with healed single blaze bears N 69° E, 58.1 feet. Record: N 67½° E.
- Fir, now 32-inch diameter with healed single blaze bears Record: S 54° E, 118.8 feet.
- Cedar, now 16-inch diameter with healed single blaze bears Record: N 13° W, 30.0 feet.

Marked new bearing trees "CS" "BT" and took measurements to center of trees at lower blaze:

- White Pine 9-inch diameter bears S 63¼° W, 14.6 feet.
- Douglas Fir 7-inch diameter bears N 80¾° E, 28.0 feet.

Corner lies approximately 150 feet northeasterly gravel road 3-way intersection.

July 6, 2006

H. Durkee

B. Beeman

Roger R. Roberts

Jackson County Surveyor

P. - 103

V. - 17°40'