

FIRST RE-ESTABLISHMENT

GCDB 440400

Quarter corner common to Sections 15 and 22, Township 39 South, Range 4 East, W.M.

Found at the corner position, exposed 8 ins. in a mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1966, marked:

T37S R4E
S15
¼—
S22
1966

Bearing trees recorded by the BLM in 1966, found with healed single blazes and meas. to center at base:

- Fir snag brs. N 14° W, 72.4 ft. Record; 71.9 ft.
- W. fir, now 21 ins. diam. brs. S 16½° W, 27.1 ft. Record; S 17° W.

Mark new bearing trees "CS" "BT" and take measurements to center of trees at lower blaze:

- W. fir 6 ins. diam. brs. S 32¾° E, 29.1 ft.
- P. pine 7 ins. diam. brs. N 34° E, 66.8 ft.
- P. pine 5 ins. diam. brs. N 36¾° W, 48.7 ft.

Corner lies approx. 250 ft. north of old cinder logging road.

September 9, 2009

H. Durkee
B. Beeman

Kerry K. Bradshaw
Jackson County Surveyor

P. – 208
V. – 16°15'