

FIRST RE-ESTABLISHMENT

GCDB 440500

Quarter corner common to Sections 10 and 15, Township 39 South, Range 4 East, W.M.

Found at the corner position, exposed 8 ins. in a mound of stones, the 2½ ins. diam. galv. Iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1966, marked:

T39S R4E
S10
¼—
S15
1966

Single remaining original bearing tree recorded by P. Applegate of the GLO in 1893:

- A W. fir, now 21 ins. diam. opened and re-healed blazes brs. S 8½° W, 16.8 ft. to center at base. Record; S 6½° W, 16.5 ft.

Bearing tree recorded by the BLM in 1966:

- A fir, dead, down and rotted, brs. record; N 63° W, 47.2 ft. to center of stump hole.

Mark new bearing trees "CS" "BT" and take measurements to center of trees at lower blaze:

- P. pine 10 ins. diam. brs. N 8¼° E, 42.4 ft.
- P. pine 9 ins. diam. brs. N 52¾° W, 54.6 ft.
- W. fir 7 ins. diam. brs. S 7¾° E, 44.8 ft.

Corner lies approx. 170 ft. south of gravel road.

May 27, 2008
H. Durkee

Roger R. Roberts
Jackson County Surveyor

P. – 105
V. – 16°10'