

**FIRST RE-ESTABLISHMENT
CORNER COMMON TO SECTIONS 34 AND 35 ONLY
GCDB 500100**

Standard corner common to Sections 34 and 35, Township 39 South, Range 4 East, W.M. $V = 23^\circ$

Found in a mound of stone, a $\frac{5}{8}$ -inch re-steel rod, projecting 9 inches with aluminum cap marked:

T39S R4E
34 | 35

1974
ORLS 661

I removed the aluminum cap, deposited same alongside, and drove a 1 x 36-inch Galvanized iron pipe over said re-steel rod, 27 inches in the ground with a 2½-inch disc marked:

Jackson County 1974
T39S R4E
S34 | S35

S.C.
T40S

Original BTs marked by E.T.T. Fisher, in 1858, found as follows:

- A rotted Pine stump, approximately 40-inch diameter, scribed "BT" in exposed face bears Record: $N75^\circ E$, 31.02 feet.
- A rotted Fir stump approximately 40-inch diameter bears Record: $S70^\circ E$, 23.10 feet.
- The base of an 8-inch diameter Cedar snag, scribed "S" in partially exposed upper face bears Record: $S40^\circ W$, 39.60 feet.
- The original NW BT is now gone.

I marked the following trees CS BT and took measurements to center of trees at lower blaze:

- A Sugar Pine, 8-inch diameter bears $N23^\circ E$, 39.16 feet.
- A White Fir, 6-inch diameter bears $S50^\circ E$, 28.52 feet.
- A White Fir, 9-inch diameter bears $S39\frac{1}{2}^\circ W$, 42.92 feet.
- A White Fir, 7-inch diameter bears $N8\frac{1}{2}^\circ W$, 47.13 feet.

A recent blazed line runs West from corner.

December 9, 1974
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor