

## FIRST RE-ESTABLISHMENT

GCDB 500200

Section corner common to Section 26, 27, 34 and 35, Township 39 South, Range 4 East, W.M.  
V = 19°

From the following evidence at the location described below, I set a 1 x 36-inch Galvanized iron pipe 24 inches in the ground with a 2½-inch bronze disc marked:

Jackson County 1975	
T39S R4E	
27	26
-----	
34	35

Original BTs recorded by S. Truax in 1859, found as follows:

- Cedar, 46-inch diameter, with healed blazes bears Record: N70°E, 9.24 feet to estimated lower face. Re-measure 10.24 feet to center of tree.
- Rotted Fir stump remains found at record location of original SE BT.
- Rotted Pine stump, about 24-inch diameter bears record, S33°W, 29.04 feet to estimated lower face.
- Cedar stump, 32-inch diameter bears Record: N81°W, 28.38 feet to estimated face of healed lower blaze.

I marked new trees CS BT and took measurements to center of trees at lower blaze:

- Douglas Fir, 9-inch diameter bears S41°E, 24.90 feet.
- Douglas Fir, 12-inch diameter bears S25½°W, 62.00 feet.
- White Fir, 11-inch diameter bears N58½°W, 45.45 feet.

Corner lies 360 feet East of location marker on 5-inch diameter White Fir, alongside road.

July 29, 1975  
B. Malotte  
R. Frost

Approved by: Edward McGinty  
County Surveyor

**NEXT PAGE FOR SECOND RE-ESTABLISHMENT**

## SECOND RE-ESTABLISHMENT

GCBD 500200

Section corner common to Sections 26, 27, 34 and 35, Township 39 South, Range 4 East, W.M.

Corner monument destroyed by logging. From the following evidence, set at the corner position, a 1x30-inch flanged galvanized iron pipe with attached 2½-inch diameter brass cap marked:

### JACKSON COUNTY SURVEYOR

T39S	R4E
S27	S26
-----	
S34	S35
2002	

Original bearing trees recorded by Sewall Truax in 1859, found measured to center of tree at lower blaze:

- A cedar, now a sawed stump 46-inch diameter bears N70°E, 10.24 feet. Record: 9.24 feet to face of lower blaze.
- A cedar, now a sawed stump 32-inch diameter bears N81°W, 29.2 feet. Record: 28.38 feet to face of lower blaze.

Bearing trees marked on First Re-establishment in 1975, found and measured to center of tree at lower blaze:

- Douglas Fir, now a sawed stump 20-inch diameter with healed lower blaze bears Record: S25½°W, 62.00 feet.
- Douglas Fir, now a sawed stump 16-inch diameter with healed lower blaze bears Record: S41°E, 24.90 feet.

Marked new trees "CS" "BT" and took measurements to center of tree at lower blaze:

- Douglas Fir 7-inch diameter bears N41½°W, 5.05 feet.
- White Fir 7-inch diameter bears S34½°E, 29.75 feet.
- White Fir 8-inch diameter bears S7½°W, 59.35 feet
- No other trees within limits.

Corner lies approximately 350 feet east of dirt road. Search Coordinates - 42°08'30.6"  
122°19'35.7"

March 21, 2002

H. Durkee

T. Newcomb

Roger Roberts

Jackson County Surveyor

P. -43

V.-15½°