

## FIRST RE-ESTABLISHMENT

GCDB 500300

Section corner common to Sections 22, 23, 26 and 27, Township 39 South, Range 4 East, W.M.

Found at the corner position, exposed 4 ins. in a mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1967, marked:

T39S R4E  
S22 | S23  
—+—  
S27 | S26  
1967

Original bearing trees recorded by S. Truax of the GLO in 1859, found and measured to estimated face:

- Rotted pine remains with scribe marks "BT" on a weathered face, br. record; N 50° E, 35.6 ft.
- Pine high-stump 24 ins. diam., brs. S 11° W, 11.2 ft. Record; S 12° W.
- Rotted Fir remains, br. record; N 22° W, 11.2 ft.

Bearing trees recorded by the BLM in 1967, found with healed single blazes and measured to center at base:

- D. Fir, now 14 ins. diam. brs. record; N 13° E, 17.2 ft.
- D. Fir, now 14 ins. diam. brs. record; S 55° E, 9.6 ft.
- W. Fir, 24 ins. diam., dead and down, brs. record; N 41° W, 29.7 ft. to center of root hole.

Mark new bearing trees "CS" "BT" and take measurements to center at lower blaze:

- W. Fir 9 ins. diam. brs. N 38½° W, 7.9 ft.
- W. Fir 5 ins. diam. brs. S 56½° W, 6.7 ft.

Corner lies approx. S 45° E, 100 ft. from "Y" in dirt spur roads.

September 4, 2012

H. Durkee

Scott Fein  
Deputy Jackson County  
Surveyor

P. – 38

V. – 14°20'