

FIRST RE-ESTABLISHMENT

GCDB 500340

Quarter corner common to Sections 22 and 23, Township 39 South, Range 4 East, W.M.

Found at the corner position, exposed 5 ins. in a mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1966, marked:

T39S R4E
¼
S22 | S23
1966

Original bearing trees recorded by S. Truax of the GLO in 1859, found and measured to center at base:

- P. Pine, now 32 ins. diam. with an opened weathered face, brs. record; N 62° E, 50.2 ft.
- Remains of a sawed Pine stump, br. record; S 40° W, 9.2 ft.

Bearing trees recorded by the BLM in 1966, found with healed single blazes and measured to center at base:

- D. Fir, now 26 ins. diam., brs. N 77½° E, 15.8 ft. Record; N 80° E.
- D. Fir, now 23 ins. diam., brs. record; S 25½° W, 25.7 ft.

Mark new bearing tree "CS" "BT" and take measurement to center of tree at lower blaze:

- W. Fir 8 ins. diam. brs. N 26½° W, 55.9 ft.

Corner lies in a hunter camp approx. 60 ft. west of a gravel road.

October 30, 2012

H. Durkee

Scott Fein
Deputy Jackson County
Surveyor

P. – 69
V. – 14°