

FIRST RE-ESTABLISHMENT

GCDB 500400

Section corner common to Sections 14, 15, 22 and 23, Township 39 South, Range 4 East, W.M.

Corner monument set by the BLM in 1966 destroyed by logging.

From the following evidence:

Set at the corner a 1 x 36-inch Galvanized iron pipe, in a mound of stones and 30 inches deep, with a 2½-inch diameter brass cap cemented in the top and marked:

JACKSON COUNTY SURVEYOR	
T39S	R4E
S15	S14
— —	
S22	S23
2002	

Single remaining original bearing tree recorded by Sewall Truax in 1859, a sawed cedar stump 36-inch diameter bears record, S40° W, 45.54 feet to face of lower blaze.

Bearing trees recorded by the BLM in 1966 found and measured to center of tree at base:

- A cedar now 19-inch diameter high-stumped with a healed blaze bears record, N 11° E, 48.84 feet.
- A Douglas Fir now 13-inch diameter with a healed blaze bears S 68° E, 29.04 feet. Record: S 67° E.

Marked new trees "CS" "BT" and took measurements to center of tree at lower blaze:

- A Douglas Fir 12-inch diameter bears S 32° E, 25.94 feet.
- A Douglas Fir 4-inch diameter bears N 76½° W, 26.85 feet.
- A cedar 4-inch diameter bears N 5½° W, 36.88 feet.

Corner lies southwesterly approximately 60 feet from road.

April 12, 2002

H. Durkee

T. Newcomb

Roger R. Roberts

Jackson County Surveyor

P. - 79

V. - 15°