


**FIRST RE-ESTABLISHMENT**

**GCDB 600700**

Section corner common to Sections 35 and 36, Township 38 South, and Sections 1 and 2, Township 39 South, Range 4 East, W.M.

Found at the corner position, exposed 5 inches and in a mound of stones, the 1-inch diameter galvanized iron pipe with a 2½-inch diameter brass cap set by the BLM in 1973, marked:



Single remaining original bearing tree recorded by Sewall Truax of the GLO in 1859, a sawed, rotted Sugar Pine stump bears Record: S 67° W, 59.1 feet to estimated face.

Bearing trees recorded by the BLM in 1973, found with healed double blazes and measured to center of trees at base:

- Douglas Fir, now 16-inch diameter bears Record: N 81° E, 32.7 feet.
- Cedar, now 20-inch diameter bears Record: N 31° W, 45.9 feet.
- Fir, dead, down and rotted bears Record: S 26° W, 24.7 feet to center of stump hole.

Marked new bearing trees "CS" "BT" and took measurements to center of trees at lower blaze:

- Douglas Fir 8-inch diameter bears S 81° E, 14.1 feet.
- White Fir 9-inch diameter bears S 39¼° W, 23.4 feet.

Corner lies approximately 50 feet northeasterly from graveled logging road.

October 9, 2006

H. Durkee

B. Beeman

Roger R. Roberts

Jackson County Surveyor

P. - 176

V. - 16°15'