

## FIRST RE-ESTABLISHMENT

### GCDB 700200

Section corner common to Sections 25 and 36, Township 39 South, Range 4 East and Sections 30 and 31, Township 39 South, Range 5 East, W.M.

Found at the corner position, exposed 6 ins. in a mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1976, marked:

T39S  
R4E R5E  
S25 | S30  
—+—  
S36 | S31  
1976

Original bearing trees recorded by Sewall Truax of the GLO in 1859, found and measured to center at base:

- Sawed burnt pine stump 36 ins. diam. S18°W, 55.5 ft. record; 54.5 ft. to face.
- Sawed pine stump 36 ins. diam. brs. N35°W, 15.3 ft. Record; 14.2 ft. to face.

Bearing trees recorded by the BLM in 1976, found with healed single blazes and measured to center at base:

- D. Fir, now 27 ins. diam. brs. record; S21½°E, 101.0 ft.
- Cedar, now 19 ins. diam. brs. record; S15½°W, 90.4 ft.
- P. pine, now 19 ins. diam. brs. record; N32°W, 128.4 ft.

Mark new bearing tree "CS" "BT" and take measurement to center of tree at lower blaze:

- P. Pine 7 ins. diam. brs. N43¼°E, 28.2 ft.

Corner lies approx. 250 ft. west of old cinder road.

June 27, 2011

H. Durkee

Kerry Bradshaw  
Jackson County Surveyor

P. – 104

V. – 15°20'