

FIRST RE-ESTABLISHMENT

GCDB 700300

Section corner common to Section 24 and 25, Township 39 South, Range 4 East and Sections 19 and 30, Township 39 South, Range 5 East, W.M. $V = 19\frac{3}{4}^\circ$

From the following evidence at the location described below I set a 1 x 36-inch Galvanized iron pipe 24 inches in the ground with a 2½-inch bronze disc marked:

Jackson County 1975
T39S
24 | 19
—+—
25 | 30
R4E R5E

Original BTs recorded by S. Truax in 1859, found as follows:

- A sawed Sugar Pine stump, 50-inch diameter, containing scribed partial "BT" in burned lower face bears Record: N51°E, 97.02 feet to scribed face.
- A rotted Fir found at record location of original SE BT.
- The remains of a Sugar Pine stump, about 50-inch diameter bears Record: S80°W, 89.76 feet to estimated face.
- The burned sawed stump, 60-inch diameter, of a down and burned Sugar Pine bears Record: N81°W, 85.14 feet to estimated face.

I marked new trees CS BT and took measurements to center of trees at lower blaze:

- Sugar Pine, 21-inch diameter bears N26°E, 57.30 feet.
- Douglas Fir, 26-inch diameter bears S61½°E, 28.15 feet.
- Ponderosa Pine, 10-inch diameter bears S66°W, 13.58 feet.
- Douglas Fir, 18-inch diameter bears N49°W, 27.53 feet.

Corner lies in old skid trail, about 600 feet North of location marker on 6-inch diameter Cedar, alongside road.

August 20, 1975
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor