

FIRST RE-ESTABLISHMENT

GCDB 700500

Section corner common to Sections 12 and 13, Township 39 South, Range 4 East, and Sections 7 and 18, Township 39 South, Range 5 East, W.M. $V = 19^\circ$

From the following evidence, at the location described below, I set a 1 x 36-inch Galvanized iron pipe 24 inches in the ground with a 2½-inch bronze disc marked:

Jackson County 1975

T39S	
12	7
<hr/>	
13	18
R4E	R5E

Original BTs recorded by S. Truax in 1859, found as follows:

- The stump remains of a down Pine, 30-inch diameter, containing scribed "B" and partial "T" bears record, N55°E, 38.28 feet.
- The base of a down Pine, 11-inch diameter, scribed "T39S 18" and "BT" bears Record: S47°E, 13.2 feet.
- The base of a down Fir, about 28-inch diameter, containing old axe work bears Record: S18°W, 7.26 feet.
- White Fir, 41-inch diameter, with healed blazes bears Record: N80°W, 41.58 feet to estimated lower face. Re-measure, 42.27 feet to center of tree.

I marked new trees CS BT and took measurements to center of trees at lower blaze:

- Douglas Fir, 10-inch diameter bears East, 15.0 feet.
- White Fir, 10-inch diameter bears S24°E, 13.1 feet.
- Douglas Fir, 7-inch diameter bears S46°W, 28.7 feet.
- Douglas Fir, 8-inch diameter bears N62½°W, 10.45 feet.

Corner lies about 1,000 feet North of location marker on 18-inch diameter White Fir, alongside road C. East-West.

August 26, 1975
Ed Graham
B. Malotte

Approved by: Edward McGinty
County Surveyor

SEE NEXT PAGE SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 700500

Section corner common to Sections 12 and 13 of Township 39 South, Range 4 East and Sections 7 and 18 of Township 39 South, Range 5 East, W.M.

Found at the corner position, exposed 8 ins., the 1 in. diam. galv. iron pipe with a 2½ ins. diam. brass cap set on 1st Re-establishment in 1975 and marked:

Jackson County 1975

T39S

12 | 7

— | —

13 | 18

R4E R5E

Single remaining original bearing tree recorded by Sewal Truax of the GLO in 1859 found and measured to center of root hole;

- Fir dead, down, and rotted brs. record N80°W, 41.6 ft.

Bearing trees recorded on said 1st re-establishment in 1975 found with healed double blazes and measured to center at lower blaze;

- D. fir high stump brs. east, 14.8 ft. record; 15.0 ft.
- W. fir high stump brs. record; S24°E, 13.1 ft.
- D. fir sawed stump brs. S45°W, 28.7 ft. record; S46°W
- D. fir sawed stump brs. record; N62½°W, 10.5 ft.

Marked new bearing trees 'CS''BT' and measured to center at lower blaze;

- W. fir 8 ins. diam. brs. N31¾°E, 16.6 ft.
- W. fir 7 ins. diam. brs. S68½°E, 3.0 ft.
- W. fir 7 ins. diam. brs. N27¾°W, 7.0 ft.
- W. fir 10 ins. diam. brs. S83½°W, 12.6 ft.

Corner lies approx. 1000 ft. west of spur road

May 12, 2010

B. Beeman

H. Durkee

Kerry K. Bradshaw
Jackson County Surveyor

P. -113

V. - 14°35'