

FIRST RE-ESTABLISHMENT

GCDB 700640

Quarter corner common to Section 1, Township 39 South, Range 4 East and Section 6, Township 39 South, Range 5 East, W.M. $V = 20\frac{3}{4}^\circ$

Found, in mound of stone, a 5/8 x 30-inch re-steel rod with aluminum cap marked as reported on Survey No. 5550, dated 1973.

I replaced the above with a 1 x 36-inch Galvanized iron pipe set 24 inches in the ground with a 2½-inch bronze disc marked:

Jackson County 1975
T39S
¼S
1 | 6
R4E R5E

Original BTs recorded by S. Truax in 1859, found as follows:

- A sawed Fir stump, 35-inch diameter, containing scribe marks including "S" and "BT" in single exposed face bears record, N23°E, 9.90 feet to scribed face.
- A stump hole with Pine fragments found at record location of original SW BT.

I deposited found re-steel rod alongside corner, marked new trees CS BT and took measurements to center of trees at lower blaze:

- Douglas Fir, 7-inch diameter bears N76°E, 3.30 feet.
- Cedar, 14-inch diameter bears S59½°W, 34.40 feet.

Corner lies on blazed North-South line about 1,190 feet West of location marker on 8-inch diameter White Fir, alongside road.

August 27, 1975
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor