

**FIRST RE-ESTABLISHMENT
CORNER COMMON TO SECTIONS 5 AND 6 ONLY
GCDB 200700**

Section corner common to Section 31 and 32, Township 39 South, Range 3 West, and Section 5 and 6, Township 40 South, Range 3 West, per S. Lackland, (contract No. 429, dated 1882) now changed to "Control Corner" common to Section 5 and 6, Township 40 South, Range 3 West,
W.M. $V = 20^\circ$
77-22

Reference: Jackson County Project File No. 77-22

From the following evidence, at the location described below:

- I set a 1 x 36-inch Galvanized iron pipe, 30 inches in the ground, with a yellow plastic cap marked:

"Jackson County"
- The single remaining BT recorded by S. W. Lackland in 1882, now a Douglas Fir snag, 38-inch diameter, scribed "T40SR3WS6" in opened upper face, bears Record: S50°W, 39.60 feet to scribed face.

To further perpetuate this position, I marked the following trees CS BT and took measurements to center of trees at lower blaze:

- Laurel, 16-inch diameter, bears S19°E, 13.67 feet.
- Douglas Fir, 14-inch diameter, bears N42°W, 26.55 feet

November 11, 1977
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor