

FIRST RE-ESTABLISHMENT  
NORTH QUARTER CORNER TO SECTION 2 ONLY  
GCDB 540700

North quarter corner of Section 2 only, Township 40 South, Range 3 West, W.M.  $V = 19\frac{1}{2}^\circ$

Found, projecting 12 inches, the 1-inch diameter iron pipe with GLO brass cap marked:

$\frac{1}{4}$   
—  
2  
SC  
1917

By M. Wright on 1917 resurvey.

Bearing trees recorded by Wright found as follows:

- Douglas Fir, 18-inch diameter, with healed single blaze bears  $S17^\circ E$ , 16.65 feet to center of tree. Record:  $S16\frac{1}{2}^\circ E$ , 15.84 feet.
- Douglas Fir, 8-inch diameter, with healed single blaze bears  $S49^\circ W$ , 12.75 feet to center of tree. Record:  $S49\frac{1}{2}^\circ W$ , 12.54 feet.
- **Note:** The above trees are erroneously recorded by Wright as bearing trees to the North  $\frac{1}{4}$  of Section 1, T40S R3W.

I mark a new tree CS BT:

- Douglas Fir, 8-inch diameter bears  $N46\frac{1}{2}^\circ E$ , 6.63 feet to center of tree at lower blaze.
- The (brass cap) South  $\frac{1}{4}$  corner of Section 35 bears  $S89\frac{1}{2}^\circ E$ , 55.11 feet.

Corner lies 50 feet West of dry creek bed C. South.

January 17, 1977  
B. Malotte  
R. Frost

Approved by: Edward McGinty  
County Surveyor