

FIRST RE-ESTABLISHMENT

GCDB 600540

Quarter Section Corner common between Sections 11 and 12, Township 40 South, Range 3 West, W.M.

Found stone set for corner, marked $\frac{1}{4}$ on W. face. Also dead White Oak BT to NE plainly scribed.

Set the original corner monument, a 12" x 4" x 15" stone marked $\frac{1}{4}$ on W. face, 8" in the ground, for corner at the exact location as found.

From which:

- A 14" Red Fir scribed CS BT bears $N54\frac{1}{2}^{\circ}E$, 19.7 feet.
- Scribe a 6" live Oak CS BT which bears $N79\frac{3}{4}^{\circ}W$, 44.4 feet.

Impractical to set 1-inch galvanized pipe.

C. Z. Boyden,
Deputy County Surveyor

Lester Smith, Chainman
Glenn Smith, Chainman

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 600540

Quarter corner common to Sections 11 and 12, Township 40 South, Range 3 West, W.M.

Found at the corner position, exposed 12 ins. in a large mound of stones with the original stone alongside, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1964, marked:

T40S R3W
¼
S11 | S12
1964

Bearing trees recorded on 1st Re-establishment in 1934, found and measured to center at base:

- D. Fir, now 27 ins. diam. with healed double blazes brs. N54½°E, 20.6 ft. record; 19.8 ft. to face.
- Easterly fork of a L. Oak, now 7 ins. diam. with a healed lower blaze and a rotted partially healed upper blaze brs. N79¾°W, 44.4 ft. record; 44.2 ft. to face.

Bearing trees recorded by the BLM in 1964 found with healed single blazes and measured to center at base:

- D. Fir, now 21 ins. diam. brs. record; N66°E, 58.7 ft.
- D. Fir, now 16 ins. diam. brs. record; N28°W, 13.2 ft.

Mark new bearing tree "CS" "BT" and take measurement to center of tree at lower blaze:

- D. Fir 10 ins. diam. brs. S86½°W, 6.6 ft.

Corner lies approx. 50 ft. south of USFS Road No. 20, and approx. 25 ft. north of a creek.

December 8, 2010

H. Durkee

Kerry Bradshaw
Jackson County Surveyor

P. – 235

V. – 15°40'