

**FIRST RE-ESTABLISHMENT
CORNER COMMON TO SECTIONS 1 AND 2 ONLY
GCDB 600700**

Section corner common to Sections 1 and 2, Township 40 South, Range 3 West, W.M. $V = 15\frac{3}{4}^\circ$

Found projecting 11 inches the 2-inch diameter iron pipe with GLO brass cap marked:

S	C
S2	S1
T40S R3W	

1917 by W. Wright in 1917.

Original bearing trees recorded by S. Truax in 1857 and noted by S. Lackland in 1882, and M. Wright in 1917 found as follows:

- The stump hole of a down and rotted Black Oak, about 20-inch diameter containing reverse impression of scribed "40S" and "B" bears Record: $S74^\circ E$, 50.16 feet.
- The stump hole of a down and rotted Black Oak, about 20-inch diameter containing reverse impression of scribed "0S3WS6 BT" bears Record: $S18^\circ W$, 44.22 feet on slope.
- The brass cap corner of Sections 35 and 36 bears $N86^\circ E$, 37.03 feet.

I mark the following new trees CS BT and took measurements to center of trees at lower blaze:

- The most Northerly branch, 8-inch diameter, of a double White Oak bears $S4^\circ W$, 4.30 feet.
- **Note:** No Suitable tree in SE quadrant.
- White Oak, 8-inch diameter bears $S84\frac{1}{2}^\circ W$, 20.60 feet.

Corner lies on N-S ridge top.

January 17, 1977
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor