

FIRST RE-ESTABLISHMENT

GCDB 300600

Section corner common to Sections 4, 5, 8 and 9, Township 41 South, Range 2 West, W.M.

Found at the corner position, firmly set, the 17 x 10 x 9 ins. stone set by the GLO in 1908 with 5 notches on south corner and 4 notches on east corner. Replace said stone with a 1 x 30 ins. flanged galv. iron pipe with a 2½ ins. diam. brass cap, exposed 12 ins. and raised a mound of stones. Said brass cap, marked:

JACKSON COUNTY SURVEYOR
T41S R2W
S5 | S4
—+—
S8 | S9
2011

Original bearing trees recorded by E. B. Henry of the GLO in 1908, found and measured to center at base:

- Pine, down and rotted with a detached weathered face containing scribe marks "T41S R2W S4 BT", brs. record; N42°E, 58.1 ft. to center of root hole.
- P. Pine, now 39 ins. diam. with a healed single blaze, brs. S26½°E, 51.5 ft. record; S33½°E. Opened said blaze and found scribe marks "T41S R2W S9".
- Pine, down and rotted brs. record; S48°W, 120.1 ft. to center of root hole.

Mark new bearing trees "CS" "BT" and take measurements to center of trees at lower blaze:

- P. Pine 6 ins. diam. brs. N5°W, 22.1 ft.
- P. Pine 5 ins. diam. brs. N38°E, 21.9 ft.
- P. Pine 11 ins. diam. brs. S58°W, 6.2 ft.

Corner lies approx. 150 ft. southwesterly from ridge top at southeasterly corner of bare hillside and approx. 1000 ft. westerly from top of "Yellow Jacket Mountain".

October 19, 2011

H. Durkee
S. Beecher

Kerry Bradshaw
Jackson County Surveyor

P. – 62
V. – 14°10'