

FIRST RE-ESTABLISHMENT

GCDB 300640

Quarter corner common to Sections 4 and 5, Township 41 South, Range 2 West, W.M.

From the following evidence, set at the corner position, a 1 x 30 ins. flanged galv. iron pipe with a 2½ ins. diam. brass cap, exposed 14 ins. in a large mound of stones, and marked:

JACKSON COUNTY SURVEYOR

T41S R2W

S5 S4

¼ • COR.

2011

Original bearing trees recorded by Eugene Henry of the GLO in 1908, found and measured to face of blazes:

- Sawed rotted fir stump containing scribe marks "¼ S5 BT" on original face, brs. record; N75°W, 56.8 ft.
- Rotted Fir stob brs. record; S65°E, 34.3 ft. to estimated face. (These record bearings and distances intersect in the center of an old mound of stones.)

Mark new bearing trees "CS" "BT" and take measurements to center of trees at lower blaze:

- D. Fir 8 ins. diam. brs. S69°E, 35.1 ft.
- P. Pine 9 ins. diam. brs. N77°E, 23.1 ft.
- P. Pine 6 ins. diam. brs. N86¾°W, 11.4 ft.
- P. Pine 8 ins. diam. brs. S29¾°W, 12.4 ft.

Corner lies approx. 200 ft. south of 4-wheel-drive spur road.

August 8, 2011

H. Durkee

Kerry Bradshaw
Jackson County Surveyor

P. – 25

V. – 15°