

## FIRST RE-ESTABLISHMENT

GCDB 500440

Quarter corner common to Sections 14 and 15, Township 41 South, Range 2 West, W.M.

Found at the corner position, exposed 16 ins. in a mound of stones, the 1 in. diam. galv. iron pipe with a 2½ ins. diam. brass cap set by the GLO in 1916, marked:

¼  
S15 | S14  
1916

Original bearing trees recorded by M. S. Wright of the GLO in 1916, found and measured to center at base:

- Sawed, rotted Fir stump brs. record; S38½°E, 34.3 ft.
- Rotted Fir remains br. record; N57½°W, 35.0 ft.

Mark new bearing trees "CS" "BT" and take measurements to center of trees at lower blaze:

- W. Fir 16 ins. diam. brs. N65°E, 42.1 ft.
- W. Fir 5 ins. diam. brs. S64¾°W, 26.8 ft.
- W. Fir 5 ins. diam. brs. S48¼°E, 34.0 ft.

Corner lies approx. 550 ft. west of gravel road.

August 16, 2011  
H. Durkee

Kerry Bradshaw  
Jackson County Surveyor

P. – 29  
V. – 15°25'

