

FIRST RE-ESTABLISHMENT

GCDB 500500

Section corner common to Sections 10, 11, 14 and 15, Township 41 South, Range 2 West, W.M.

Found at the corner position, exposed 8 ins., the 2 ins. diam. galv. iron pipe with a 2½ ins. diam. brass cap set by the GLO in 1916, marked:

T41S R2W
S10 | S11
—+—
S15 | S14
1916

Original bearing trees recorded by M. S. Wright of the GLO in 1916, found and measured to center at base:

- S. Fir snag with weathered blazes brs. N41°E, 19.4 ft. record; N55½°E, 24.4 ft.
- W. Fir, now 31 ins. diam. with partially healed upper blaze with scribe marks "41SR2W 14", brs. S45½°E, 42.0 ft. Record; S51½°E, 47.5 ft.
- S. Fir, now 46 ins. diam. with healed blazes brs. S65°W, 17.6 ft. Record; S58½°W, 10.6 ft.
- S. Fir snag with healed blazes brs. N73½°W, 16.7 ft. Record; N57°W, 10.6 ft.

Note: The position of this monument, obviously does not coincide with record bearing and distance information; however, the placement of said monument stands.

Mark new bearing trees "CS" "BT" and take measurements to center of trees at lower blaze:

- S. Fir 7 ins. diam. brs. N2½°E, 16.7 ft.
- S. Fir 5 ins. diam. brs. N78°E, 5.5 ft.

Corner lies approx. 200 ft. southwesterly from culvert across spur road.

July 7, 2011

H. Durkee

Kerry Bradshaw
Jackson County Surveyor

P. – 2

V. – 15°30'