

FIRST RE-ESTABLISHMENT

GCDB 500700

Section corner common to Sections 34 and 35, Township 40 South, and Sections 2 and 3, Township 41 South, Range 2 West, W.M.

Found at the corner position, exposed 8 ins. in a mound of stones, the 2 ins. diam. galv. iron pipe with a 2½ ins. diam. brass cap set by the GLO in 1916, marked:

T40S R2W
S34 | S35
—+—
S3 | S2
T41S
1916

Original bearing trees recorded by M. Wright of the GLO in 1916, found and measured to center at base:

- Fir, now 34 ins. diam. with scribe marks "S35 T40" in opened blaze, brs. record; N21½°E, 23.8 ft.
- Fir, now a snag 50 ins. diam. brs. record; S6¾°W, 191.4 ft.
- Fir, now 33 ins. diam. with scribe marks "2 34" in a partially healed blaze, brs. record; N35½°W, 23.8 ft.

Mark new bearing trees "CS" "BT" and take measurements to center of trees at lower blaze:

- W. Fir 9 ins. diam. brs. S59°E, 9.2 ft.
- W. Fir 6 ins. diam. brs. S56°W, 18.7 ft.

Corner lies approx. 700 ft. south of granite road. (USFS 20)

July 26, 2012

H. Durkee

Scott Fein

Deputy Jackson County Surveyor

P. – 15

V. – 14°40'