

FIRST RE-ESTABLISHMENT

GCDB 700600

Section corner common to Sections 6 and 7, Township 41 South, Range 1 West and Sections 1 and 12, Township 41 South, Range 2 West, W.M.

Found at the corner position, exposed 4 ins. in a ring of stones, the 2 ins. diam. galv. pipe with a 2½ ins. diam. brass cap set by the GLO in 1916, marked:

T41S
S1 | S6
—+—
S12 | S7
R2W R1W
1916

Single remaining original bearing tree recorded by M. S. Wright of the GLO in 1916,

- A Fir snag with scribe marks “/4 BT” in partially healed blaze brs. N21½°W, 83.8 ft. to center at base. Record; N26°W.

Bearing tree recorded by the BLM in 1963, found with a healed single blaze and measured to center at base:

- Fir, now 21 ins. diam. brs. record; N74°E, 97.0 ft.
- Three ft. high mound of stones recorded as re-built by the BLM in 1963, now scattered down the slope of the hill.

Mark new bearing tree “CS” “BT” and take measurement to center of tree at lower blaze:

- Hemlock 8 ins. diam. brs. N25½°W, 35.8 ft.
- No trees available in south quadrants.

Corner lies on 65% easterly slope approx. 400 ft. east of gravel road.

September 8, 2011

H. Durkee

Kerry Bradshaw
Jackson County Surveyor

P. – 46

V. – 15°10'