

FIRST RE-ESTABLISHMENT

GCDB 140200

Quarter corner common to Sections 30 and 31, Township 32 South, Range 1 West, W.M.

At the corner found firmly set, the original 16x13x8-inch stone marked "¼" on North face by R. Moore in 1883.

Replaced said stone with and deposited it alongside a 1x36-inch galvanized iron pipe, set 26 inches in the ground, with a 2½-inch diameter bronze cap marked:

JACKSON COUNTY 1982
T32S R1W
30
¼S —
31

- The single remaining original bearing tree, a Madrone, now 14-inch diameter with scribe mark found in (re)healed edge of axed and/or rotted out face bears S40°W, 5.64 feet to scribe mark. Record: S35°W, 5.94 feet.
- A stump hole found at record location of original Northwest bearing tree.

Marked new trees "CS" "BT" and took measurements to center of trees at lower blaze:

- White Oak, 10-inch diameter bears S64°W, 40.00 feet (12.19 m).
- Black Oak, 14-inch diameter bears N46°W, 21.95 feet (6.69 m).

Corner lies on 20% South slope and about 110 feet west of draw C. S45°W.

May 10, 1982
R. Frost
R. Templin

Edward McGinty
County Surveyor

V = 16½°
P. -66