

FIRST RE-ESTABLISHMENT

GCDB 300140

Quarter corner common to Sections 32 and 33 of Township 32 South, Range 1 West, W.M.

Found at corner position, exposed 8 ins., the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1966 and marked:

T32SR1W
¼
S32 | S33
1966

Original bearing trees recorded by Rufus Moore of the GLO in 1883 found with healed blazes and measured to center at base;

- W. oak now 23 ins. diam. with rotted upper blaze, brs. S41¼°E, 32.2 ft. record; 31.7 ft. to face
- W. oak snag brs. S50¼°W, 28.5 ft. record 27.7 to face

Bearing trees recorded by the BLM in 1966 found with partially healed single blazes and measures to center at base;

- Fir rotted stob with scribe '1/4 S33' brs. record S78°E, 19.8 ft.
- Fir rotted stob with scribe '1/4 S' brs. record S43°W, 13.9 ft.

Bearing trees recorded by the BLM in 1985 found and measured to center at base;

- W. oak now 8 ins. diam. with a healed single blaze brs. S37°E, 3.7 ft. record; 4.0 ft.
- Cedar snag with a partially healed single blaze brs. N47°W, 41.0 ft. record; 40.6 ft.

Marked new bearing trees "CS" "BT" and measured to center at lower blaze:

- W. oak 9 ins. diam. brs. N15½°W, 6.7 ft.
- B. oak 8 ins. diam. brs. N17°E, 8.1 ft.
- W. oak 5 ins. diam. S88¼°W, 15.2 ft.

Corner lies approx. 120 ft. west of gravel road

April 1, 2010

B. Beeman

H. Durkee

Kerry K. Bradshaw

Jackson County Surveyor

P. – 72

V. – 16°