

**RE-ESTABLISHMENT (by Douglas County)**

**ANGLE POINT**

**GCDB 603700**

This corner lies 61.4 feet W. of  $\frac{1}{4}$  corner Section 36, Township 31-1 West, which is a Brass Cap, 1923, in good condition (tagged BTs).

**Found:**

- No trace of Stone at corner.
- Original 12" Douglas Fir, now dead, S.25°E. 13.0 feet (Record: S.32°E. 14.5') scribe visible "AP BT".
- Original 16" now 16" Douglas Fir N.71°E. 36.3 feet.

**Set Brass Cap at Angle Point Marked:**

County Surveyor's Office

Doug Co

T31S R1W

A P

1968

T32S

—

Jack Co

**New BT:**

- 38" Douglas Fir S.49°E. 22.0 feet Marked A.P. CS BT.

July & August 1968

John M. Powell

Frank Jones

W. Penley