

FIRST RE-ESTABLISHMENT

GCDB 700440

Quarter corner common to Section 13, Township 32 South, Range 1 West, and Section 18, Township 32 South, Range 1 East, W.M.

Found at the corner position, exposed 6 ins. and in a mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1966, marked:

T32S
R1W ¼ R1E
S13 | S18
1966

Single remaining original bearing tree recorded by Rufus Moore of the GLO in 1883,

- A d. fir, now 50 ins. diam. and scorched with healed blazes brs. N 80° W, 16.6 ft. to center at base. Record; 14.5 ft. to face.

Bearing tree recorded by the BLM in 1966,

- A d. fir, now 24 ins. diam. with a healed single blaze brs. record; N 4° W, 26.4 ft. to center at base.

Mark new bearing tree "CS" "BT" and take measurement to center of tree at lower blaze:

- D. fir 10 ins. diam. brs. S 78¾° E, 19.2 ft.

No trees within limits in northeast quadrant.

Corner lies approx. 100 ft. east of gravel spur road and approx. 15 ft. west of small creek.

May 13, 2008

H. Durkee
B. Beeman

Roger R. Roberts
Jackson County Surveyor

P. – 96
V. – 14°45'